



Philips Firmware Upgrade Information

Upgrade for type:	ED8DVDRWK/00 ED8DVDRWK/05	→ Drive type number on label. (UK)
Upgrade for string:	ED8DVDRW	→ Drive name as seen in Windows [™]
From firmware:	V5Sx	
To new firmware:	V5S4	
Date:	14 October 2005	

Version History

Changes from firmware V5S3 to V5S4

- Released 14 October 2005.
- Improved writing quality on several DVD+R, DVD+R Double Layer, DVD+RW, DVD-R and DVD-RW media.
- Added a temperature measurement which prevents overheating when writing DVD+R Double Layer, which could cause bad writing quality on DVD+R Double Layer discs.



Philips does not and can not warrant the performance of/the results you may obtain using this software. At no time, Philips can held liable for any damages including (but not limited to) lost profits or consequential damages or for any claim by any other party.